ļ	Туре	L #	Hits	Search Text	DBs
1	BRS	L1	220052	pressure near2 (sensor detector transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L2	24669	1 and (diaphragm)	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L3	29960	pressure near2 (sensor detector transducer measur\$5).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L4	2788	3 and (diaphragm).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L5	33	4 and (elastomer).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	1	5 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
7	BRS	L7	742	4 and (circuit\$5).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
8	BRS	L8	365	7 and (fluid liquid).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
9	BRS	L9	20	8 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
10	BRS	L10	4	9 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
11	BRS	Lll	5295	pressure near2 transmitter	USPAT; US-PGPUB; EPO; JPO; DERWENT
12	BRS	L12	104	11 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
13	BRS	L13	15	12 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
14	BRS	L14	7	13 and (diaphragm)	USPAT; US-PGPUB; EPO; JPO; DERWENT
15	BRS	L15	18	"6050145"	USPAT; US-PGPUB; EPO; JPO; DERWENT
16	BRS	L16	1	15 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
17 -	BRS	L17	0	16 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
18	BRS	L18	1091	pressure near2 transmitter.ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT
19	BRS	L19	8	18 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
20	BRS	L20	1	19 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Tim Stamp	Comments	Error D finition	Erro
1	2004/05/06 10:49			0
2	2004/05/06 10:45			0
3	2004/05/06 10:39			0
4	2004/05/06 10:39			0
5	2004/05/06 10:41			0
6	2004/05/06 10:41			0
7	2004/05/06 10:41			0
8	2004/05/06 10:41			0
9	2004/05/06 10:45			0
10	2004/05/06 10:45			0
11	2004/05/06 10:46			0
12	2004/05/06 10:46			0
13	2004/05/06 10:46		-	0
14	2004/05/06 10:53			0
15	2004/05/06 10:45			0
16	2004/05/06 10:46			0
17	2004/05/06 10:46			0
18	2004/05/06 10:48			0
19	2004/05/06 10:48			0
20	2004/05/06 10:48			0

	Туре	L#	Hits	Search Text	DBs
21	BRS	L21	0	20 and (pressure) near2 (sensor detector transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
22	BRS	L22	626	pressure near2 transmitter.clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
23	BRS	L23	20	22 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
24	BRS	L24	2	23 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
25	BRS	L25	2	24 and (pressure) near2 (sensor detector transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
26	BRS	L26	166137	73/\$9.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT
27	BRS	L27	1078	26 and pressure near2 transmitter	USPAT; US-PGPUB; EPO; JPO; DERWENT
28	BRS	L28	21	27 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
29	BRS	L29	0 -	28 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
30	BRS	L30	22660	26 and (pressure) near2 (sensor detector transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
31	BRS	L31	513	30 and (elastomer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
32	BRS	L32	51	31 and (polyurethane)	USPAT; US-PGPUB; EPO; JPO; DERWENT
33	BRS	L33	11	32 and (diaphragm)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
21	2004/05/06 10:48			0
22	2004/05/06 10:50			0
23	2004/05/06 10:50			0
24	2004/05/06 10:50			0
25	2004/05/06 10:50			0
26	2004/05/06 10:50			0
27	2004/05/06 10:50		· · · · · · · · · · · · · · · · · · ·	0
28	2004/05/06 10:50		÷	0
29	2004/05/06 10:50			0
30	2004/05/06 10:50		·	0
31	2004/05/06 10:50			0
32	2004/05/06 10:50		· ·	0
33	2004/05/06 10:51			0